School Name	Work
Basswood ES	Safety & Security Upgrades
	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	HVAC Upgrades/Additions in MDF and IDF rooms
	Technology Hardware Replacement
	Expand/Upgrade Student and Staff technology devices
Bette Perot ES	Safety & Security Upgrades
	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	HVAC Upgrades/Additions in MDF and IDF rooms
	Technology Hardware Replacement
	Expand/Upgrade Student and Staff technology devices
Bluebonnet ES	Safety & Security Upgrades
5.0.0000120	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	HVAC Upgrades/Additions in MDF and IDF rooms
	Primary Power and UPS Upgrades in MDF/IDF
	Technology Hardware Replacement
	Expand/Upgrade Student and Staff technology devices
	Special Education Classroom Renovations
	Special Education Classiconn Nethovations



Caprock ES	Safety & Security Upgrades
Capiock L3	Raptor Scanner Upgrades
	Vestibule Check-In System
	•
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	 Primary Power and UPS Upgrades in MDF/IDF
	 Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices
Eagle Ridge ES	Safety & Security Upgrades
	 Raptor Scanner Upgrades
	 Vestibule Check-In System
	 Security Vestibule Rework
	 Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	 Additional Security Cameras
	 Classroom Intercom Upgrades
	Technology Upgrades
	 Upgrade/Increase network infrastructure and Wi-Fi access
	 Primary Power and UPS Upgrades in MDF/IDF
	 Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices
Florence ES	Replacement school on site next to existing campus
Freedom ES	Safety & Security Upgrades
	 Raptor Scanner Upgrades
	 Vestibule Check-In System
	 Security Vestibule Rework
	 Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	 Upgrade/Increase network infrastructure and Wi-Fi access
	 Primary Power and UPS Upgrades in MDF/IDF
	Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices



Γ= = .	
Friendship ES	Safety & Security Upgrades
	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	 Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	Additional Security Cameras
	 Classroom Intercom Upgrades
	Technology Upgrades
	 Upgrade/Increase network infrastructure and Wi-Fi access
	 Primary Power and UPS Upgrades in MDF/IDF
	 Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices
Heritage ES	Replacement school on site next to existing campus
Hidden Lakes ES	Safety & Security Upgrades
	Raptor Scanner Upgrades
	 Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	Primary Power and UPS Upgrades in MDF/IDF
	Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices
Independence ES	Safety & Security Upgrades
•	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrade
	Upgrade/Increase network infrastructure and Wi-Fi access
	HVAC Upgrades/Additions in MDF and IDF rooms
	Technology Hardware Replacement
	Expand/Upgrade Student and Staff technology devices
	- Expand/ Opprade Stadent and Stan technology devices



Kallan Hamial FC	Cafatu Q Caguritu Unguadas
Keller-Harvel ES	Safety & Security Upgrades
	Raptor Scanner Upgrades Marking to Charles to Scanner
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	 Primary Power and UPS Upgrades in MDF/IDF
	 Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices
	Special Education Classroom Renovations
Liberty ES	Safety & Security Upgrades
	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	Additional Security Cameras
	 Classroom Intercom Upgrades
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	 Provide New MDF/IDF closets
	 Primary Power and UPS Upgrades in MDF/IDF
	 Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices
Lone Star ES	Safety & Security Upgrades
	 Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	Additional Security Cameras
	 Classroom Intercom Upgrades
	Technology Upgrades
	 Upgrade/Increase network infrastructure and Wi-Fi access
	 Primary Power and UPS Upgrades in MDF/IDF
	 Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices



Safety & Security Upgrades
Vestibule Check-In System Security Vestibule Rework Ballistic Film on Glazing at Strategic Locations Access Controls Expansion and Upgrades Additional Security Cameras Classroom Intercom Upgrades MEP & Life Safety Upgrades Pkg 1 HVAC System Replacement Primary Power Equipment Replacement Fire Alarm System Replacement PA System Replacement PA System Replacement Upgrades Upgrades Upgrades/Increase network infrastructure and Wi-Fi access HVAC Upgrades/Additions in MDF and IDF rooms Primary Power and UPS Upgrades in MDF/IDF Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
Security Vestibule Rework Ballistic Film on Glazing at Strategic Locations Access Controls Expansion and Upgrades Additional Security Cameras Classroom Intercom Upgrades MEP & Life Safety Upgrades Pkg 1 HVAC System Replacement Primary Power Equipment Replacement Fire Alarm System Replacement PA System Replacement PA System Replacement Technology Upgrades Upgrade/Increase network infrastructure and Wi-Fi access HVAC Upgrades/Additions in MDF and IDF rooms Primary Power and UPS Upgrades in MDF/IDF Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
Ballistic Film on Glazing at Strategic Locations Access Controls Expansion and Upgrades Additional Security Cameras Classroom Intercom Upgrades MEP & Life Safety Upgrades Pkg 1 HVAC System Replacement Primary Power Equipment Replacement Fire Alarm System Replacement PA System Replacement PA System Replacement Technology Upgrades Upgrades Upgrade/Increase network infrastructure and Wi-Fi access HVAC Upgrades/Additions in MDF and IDF rooms Primary Power and UPS Upgrades in MDF/IDF Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
 Additional Security Cameras Classroom Intercom Upgrades MEP & Life Safety Upgrades Pkg 1 HVAC System Replacement Primary Power Equipment Replacement Fire Alarm System Replacement PA System Replacement Technology Upgrades Upgrade/Increase network infrastructure and Wi-Fi access HVAC Upgrades/Additions in MDF and IDF rooms Primary Power and UPS Upgrades in MDF/IDF Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
Classroom Intercom Upgrades MEP & Life Safety Upgrades Pkg 1 HVAC System Replacement Primary Power Equipment Replacement Fire Alarm System Replacement PA System Replacement PA System Replacement Technology Upgrades Upgrade/Increase network infrastructure and Wi-Fi access HVAC Upgrades/Additions in MDF and IDF rooms Primary Power and UPS Upgrades in MDF/IDF Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
MEP & Life Safety Upgrades Pkg 1 HVAC System Replacement Primary Power Equipment Replacement Fire Alarm System Replacement PA System Replacement Technology Upgrades Upgrade/Increase network infrastructure and Wi-Fi access HVAC Upgrades/Additions in MDF and IDF rooms Primary Power and UPS Upgrades in MDF/IDF Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
 HVAC System Replacement Primary Power Equipment Replacement Fire Alarm System Replacement PA System Replacement Technology Upgrades Upgrade/Increase network infrastructure and Wi-Fi access HVAC Upgrades/Additions in MDF and IDF rooms Primary Power and UPS Upgrades in MDF/IDF Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
 Primary Power Equipment Replacement Fire Alarm System Replacement PA System Replacement Technology Upgrades Upgrade/Increase network infrastructure and Wi-Fi access HVAC Upgrades/Additions in MDF and IDF rooms Primary Power and UPS Upgrades in MDF/IDF Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
 Fire Alarm System Replacement PA System Replacement Technology Upgrades Upgrade/Increase network infrastructure and Wi-Fi access HVAC Upgrades/Additions in MDF and IDF rooms Primary Power and UPS Upgrades in MDF/IDF Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
 PA System Replacement Technology Upgrades Upgrade/Increase network infrastructure and Wi-Fi access HVAC Upgrades/Additions in MDF and IDF rooms Primary Power and UPS Upgrades in MDF/IDF Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
Technology Upgrades Upgrade/Increase network infrastructure and Wi-Fi access HVAC Upgrades/Additions in MDF and IDF rooms Primary Power and UPS Upgrades in MDF/IDF Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
 Upgrade/Increase network infrastructure and Wi-Fi access HVAC Upgrades/Additions in MDF and IDF rooms Primary Power and UPS Upgrades in MDF/IDF Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
 HVAC Upgrades/Additions in MDF and IDF rooms Primary Power and UPS Upgrades in MDF/IDF Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
 Primary Power and UPS Upgrades in MDF/IDF Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
 Technology Hardware Replacement Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
 Expand/Upgrade Student and Staff technology devices Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
Special Education Classroom Renovations Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
Park Glen ES Safety & Security Upgrades Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
 Raptor Scanner Upgrades Vestibule Check-In System Security Vestibule Rework
Vestibule Check-In SystemSecurity Vestibule Rework
Security Vestibule Rework
·
Ballistic Film on Glazing at Strategic Locations
Access Controls Expansion and Upgrades Additional Controls
Additional Security Cameras Classes and Internal Aller and Inc.
Classroom Intercom Upgrades Technology Upgrades
Technology Upgrades • Upgrade/Increase network infrastructure and Wi-Fi access
HVAC Upgrades/Additions in MDF and IDF rooms
Technology Hardware Replacement
Expand/Upgrade Student and Staff technology devices
Special Education Classroom Renovations
Parkview ES Replacement school on existing site, phased construction



Ridgeview ES	Safety & Security Upgrades
	Raptor Scanner Upgrades
	 Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	 Upgrade/Increase network infrastructure and Wi-Fi access
	 Renovate MDF and IDF rooms
	 Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices
Shady Grove ES	Safety & Security Upgrades
	 Raptor Scanner Upgrades
	 Vestibule Check-In System
	 Security Vestibule Rework
	 Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	 Additional Security Cameras
	 Classroom Intercom Upgrades
	Technology Upgrades
	 Upgrade/Increase network infrastructure and Wi-Fi access
	 Primary Power and UPS Upgrades in MDF/IDF
	 Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices
	Special Education Classroom Renovations
Whitley Road ES	Replacement school on existing site, phased construction



Willis Lane ES	Safety & Security Upgrades
	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	MEP & Life Safety Upgrades Pkg 1
	HVAC System Replacement
	Primary Power Equipment Replacement
	Fire Alarm System Replacement
	PA System Replacement
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	Primary Power and UPS Upgrades in MDF/IDF
	Technology Hardware Replacement
	Expand/Upgrade Student and Staff technology devices
	Special Education Classroom Renovations
Woodland Springs ES	Safety & Security Upgrades
	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	Primary Power and UPS Upgrades in MDF/IDF
	Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices



Boar Crook IS	Cafoty & Cocyrity Ungrados
Bear Creek IS	Safety & Security Upgrades
	Raptor Scanner Upgrades Mactibula Charle to Scattere
	Vestibule Check-In System See it Westibule Beneath
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	MEP & Life Safety Upgrades Pkg 1 (limited areas)
	HVAC System Replacement
	 Primary Power Equipment Replacement
	Fire Alarm System Replacement
	PA System Replacement
	Technology Upgrades
	 Upgrade/Increase network infrastructure and Wi-Fi access
	 HVAC Upgrades/Additions in MDF and IDF rooms
	 Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices
	Crisis Center Addition
Chisholm Trail IS	Safety & Security Upgrades
	 Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
II	 Access Controls Expansion and Upgrades
	 Access Controls Expansion and Opgrades Additional Security Cameras
	Additional Security Cameras
	Additional Security CamerasClassroom Intercom Upgrades
	 Additional Security Cameras Classroom Intercom Upgrades MEP & Life Safety Upgrades Pkg 1 HVAC System Replacement
	 Additional Security Cameras Classroom Intercom Upgrades MEP & Life Safety Upgrades Pkg 1 HVAC System Replacement Primary Power Equipment Replacement
	 Additional Security Cameras Classroom Intercom Upgrades MEP & Life Safety Upgrades Pkg 1 HVAC System Replacement Primary Power Equipment Replacement Fire Alarm System Replacement
	 Additional Security Cameras Classroom Intercom Upgrades MEP & Life Safety Upgrades Pkg 1 HVAC System Replacement Primary Power Equipment Replacement Fire Alarm System Replacement PA System Replacement
	 Additional Security Cameras Classroom Intercom Upgrades MEP & Life Safety Upgrades Pkg 1 HVAC System Replacement Primary Power Equipment Replacement Fire Alarm System Replacement PA System Replacement Technology Upgrades
	 Additional Security Cameras Classroom Intercom Upgrades MEP & Life Safety Upgrades Pkg 1 HVAC System Replacement Primary Power Equipment Replacement Fire Alarm System Replacement PA System Replacement
	 Additional Security Cameras Classroom Intercom Upgrades MEP & Life Safety Upgrades Pkg 1 HVAC System Replacement Primary Power Equipment Replacement Fire Alarm System Replacement PA System Replacement Technology Upgrades Upgrade/Increase network infrastructure and Wi-Fi access Renovate MDF and IDF rooms
	 Additional Security Cameras Classroom Intercom Upgrades MEP & Life Safety Upgrades Pkg 1 HVAC System Replacement Primary Power Equipment Replacement Fire Alarm System Replacement PA System Replacement Technology Upgrades Upgrade/Increase network infrastructure and Wi-Fi access



Parkwood Hill IS	Safety & Security Upgrades
Turkwood Tim IS	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	, ·
	Classroom Intercom Upgrades MED 8 Life Sefety Upgrades Pkg 1
	MEP & Life Safety Upgrades Pkg 1
	HVAC System Replacement
	Primary Power Equipment Replacement Technology Ungrades
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	HVAC Upgrades/Additions in MDF and IDF rooms
	Primary Power and UPS Upgrades in MDF/IDF The second of the sec
	Technology Hardware Replacement
	Expand/Upgrade Student and Staff technology devices
	Special Education Classroom Renovations
	Crisis Center Addition
Trinity Meadows IS	Safety & Security Upgrades
	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	Additional Security Cameras
	 Classroom Intercom Upgrades
	Technology Upgrades
	 Upgrade/Increase network infrastructure and Wi-Fi access
	 Provide new MDF/IDF rooms
	 New HVAC Upgrades in MDF and IDF rooms
	 Primary Power and UPS Upgrades in MDF/IDF
	 Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices
1	1
	Special Education Classroom Renovations



Fossil Hill MS	Safety & Security Upgrades
	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	Renovate MDF and IDF rooms
	Technology Hardware Replacement
	Expand/Upgrade Student and Staff technology devices
	Fine Arts Additions and Renovations
	Core Academic Renovations
	Special Education Classroom Renovations
	Capital Improvements
Hillwood MS	Safety & Security Upgrades
	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	MEP & Life Safety Upgrades Pkg 1
	HVAC System Replacement
	Primary Power Equipment Replacement
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	Primary Power and UPS Upgrades in MDF/IDF Tack to be a series of the series of t
	Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices



Indian Springs MS	Safety & Security Upgrades
mulan springs ivis	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	·
	Ballistic Film on Glazing at Strategic Locations Access Controls Expansion and Ungrades
	Access Controls Expansion and Upgrades Addisional Security Consuma
	Additional Security Cameras Cleans and Internal actions
	Classroom Intercom Upgrades MED 8 Life Sefety Upgrades Plea 1
	MEP & Life Safety Upgrades Pkg 1
	HVAC System Replacement
	Primary Power Equipment Replacement Table 2 la 2
	Technology Upgrades
	Renovate MDF and IDF rooms
	Technology Hardware Replacement
	Expand/Upgrade Student and Staff technology devices
Keller MS	Safety & Security Upgrades
	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	 Upgrade/Increase network infrastructure and Wi-Fi access
	New MDF and IDF rooms
	 Primary Power and UPS Upgrades in MDF/IDF
	 Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices
	Fine Arts Additions and Renovations
	Academic Renovations
	Special Education Classroom Renovations
	Locker Room Renovations
	Capital Improvements



Timberview MS	Safety & Security Upgrades
	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	New HVAC in MDF and IDF rooms
	Primary Power and UPS Upgrades in MDF/IDF
	Technology Hardware Replacement
	Expand/Upgrade Student and Staff technology devices
Trinity Springs MS	Safety & Security Upgrades
inner, opringe me	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	Renovate MDF and IDF rooms
	Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices
Vista Ridge MS	Safety & Security Upgrades
_	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices



Central HS	Safety & Security Upgrades
	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	New HVAC in MDF and IDF rooms
	 Primary Power and UPS Upgrades in MDF/IDF
	Technology Hardware Replacement
	Expand/Upgrade Student and Staff technology devices
	Fine Arts Improvements
	 Auditorium Lighting Improvements
	Sound System Improvements
	Rigging System Improvements
	Special Education Classroom Renovations
	Indoor Extra-Curricular Program Facility
Fossil Ridge HS	Safety & Security Upgrades
	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	MEP & Life Safety Upgrades Pkg 1
	HVAC System Replacement
	Primary Power Equipment Replacement
	Fire Alarm System Replacement
	PA System Replacement
	Technology Upgrades
	 Upgrade/Increase network infrastructure and Wi-Fi access
	New MDF and IDF rooms
	Renovate existing MDF/IDF
	Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices
	Fine Arts Improvements
	Auditorium Lighting Improvements
	Sound System Improvements
	Rigging System Improvements
	Indoor Extra-Curricular Program Facility



Kallar HS	Safety & Security Upgrades
Keller HS	, , , , ,
	Raptor Scanner Upgrades Nactified a Charle to Systems
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	MEP & Life Safety Upgrades Pkg 1 (limited areas)
	HVAC System Replacement
	 Primary Power Equipment Replacement
	 Fire Alarm System Replacement
	PA System Replacement
	Technology Upgrades
	 Upgrade/Increase network infrastructure and Wi-Fi access
	 Relocate/Renovate MDF and IDF rooms
	 Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices Fine Arts Improvements
	Sound System Improvements
	Rigging System Improvements
	Indoor Extra-Curricular Program Facility
Timber Creek HS	Safety & Security Upgrades
	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	Primary Power and UPS Upgrades in MDF/IDF
	New HVAC in MDF and IDF rooms
	Technology Hardware Replacement
	Expand/Upgrade Student and Staff technology devices
	Fine Arts Improvements
	Auditorium Lighting Improvements
	Sound System Improvements
	Rigging System Improvements
	,
	Indoor Extra-Curricular Program Facility



NDHS/DAEP	Safety & Security Upgrades
,	Raptor Scanner Upgrades
	Vestibule Check-In System
	Security Vestibule Rework
	Ballistic Film on Glazing at Strategic Locations
	Access Controls Expansion and Upgrades
	Additional Security Cameras
	Classroom Intercom Upgrades
	Technology Upgrades
	Upgrade/Increase network infrastructure and Wi-Fi access
	New MDF and IDF rooms
	 Technology Hardware Replacement
	 Expand/Upgrade Student and Staff technology devices
Early Learning Centers	Safety & Security Upgrades
	 Raptor Scanner Upgrades
	 Vestibule Check-In System
	 Security Vestibule Rework
	 Ballistic Film on Glazing at Strategic Locations
	 Access Controls Expansion and Upgrades
	 Additional Security Cameras
	 Classroom Intercom Upgrades
	Technology Upgrades
	MDF and IDF renovations
Industrial Trades and	Includes programs with a laboratory,
Agriscience Center	shop and research space for agriscience programs,
	emerging technologies, transportation and
	logistics and trades such as construction, HVAC,
	electrical, plumbing, etc.

